



INDICATIVE CLOSED PIPE DRAINAGE DITCH CROSSING

Not to Scale



Rigghill Wind Farm  
EIA Report

**Figure 3.5a**

**Typical Closed Pipe Drainage Ditch Crossing**

Date: 05/02/2020	Drawn by: TG	Checked by: RT	Version: V1
------------------	--------------	----------------	-------------